

Date: Wednesday, 4/18/2007 10:13:14 AM
 User: Kim Johnston

Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: 412 X-TUBE INST, LOW NARROW AFT
Job Number	: 31917		
Estimate Number	: 12817		
P.O. Number	: N/A	Part Number	: D412664205
This Issue	: 4/18/2007 S.O. No. : N/A	Drawing Number	: D412-664 UNDER REV <i>OK 07.04.18</i>
Prsht Rev.	: NC	Project Number	: N/A
First Issue	: 4/17/2007 Type : LANDING GEAR	Drawing Revision	: U/R
Previous Run	: 31644	Material	: N/A
Written By	: <i>[Signature]</i>	Due Date	: 4/20/2007 Qty: 1 Um: Each
Checked & Approved By	: <i>[Signature]</i> 07.04.18		
Comment	: Est Rev: A New Issue 07-04-05 JLM		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	DC	DOCUMENT CONTROL
-----	----	------------------



Comment: DOCUMENT CONTROL

Photocopy bluefile and create labels as per PPP D412-664-205 CHG001

KS 07/04/08 ①

2.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

3.0	D412664245	CROSSTUBE ASSEMBLY, LOW NARROW AFT, 412C
-----	------------	--



Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Crosstube 412 Low

Batch: *B.31437* *07/4/10*

4.0	AN640A	Bolt
-----	--------	------



Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)

Bolt

Batch: *M19185* ✓

5.0	AN641A	Bolt
-----	--------	------



Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s)

Bolt

Batch: *M101428* ✓ *7/4/19 SP*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 4/18/2007 10:13:14 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 412 X-TUBE INST,LOW NARROW AFT

Job Number: 31917

Part Number: D412664205

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

MS21042L6

Nut



Comment: Qty.: 6.0000 Each(s)/Unit Total : 6.0000 Each(s)

Nut

Batch: M101660 ✓

7.0

AN960JD616

Washer



Comment: Qty.: 18.0000 Each(s)/Unit Total : 18.0000 Each(s)

Washer

Batch: M103395 ✓

7/4/19

SD

8.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT 100% KITS FOR COMPLETENESS

u 7/4/20 (1)

9.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

DRAFT

Identify and pack for shipping as per PPP D412-664-105

u 7/4/20

10.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



u 7.4.20

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

5.0 PARTS LIST

Item	-101	-201	-203	-105	-205	Part Number	Description
	X					D212-664-101	CROSSTUBE INSTALLATION, 204/205/210/212/214/412 HIGH FWD
		X				D212-664-201	CROSSTUBE INSTALLATION, 204/205/210/212/214 HIGH AFT
			X			D412-664-203	CROSSTUBE INSTALLATION, 412 HIGH AFT
				X		D412-664-105	CROSSTUBE INSTALLATION, 412 LOW-NARROW FWD
					X	D412-664-205	CROSSTUBE INSTALLATION, 412 LOW-NARROW AFT
1	1					D212-664-141	CROSSTUBE ASSEMBLY, 204/205/210/212/214/412 HIGH FWD
2		1				D212-664-241	CROSSTUBE ASSEMBLY, 204/205/210/212/214 HIGH AFT
3			1			D412-664-243	CROSSTUBE ASSEMBLY, 412 HIGH AFT
4				1		D412-664-145	CROSSTUBE ASSEMBLY, 412 LOW-NARROW FWD
5					1	D412-664-245	CROSSTUBE ASSEMBLY, 412 LOW-NARROW AFT
10	2			2		*D2893-1	SUPPORT
11	4			4		*D3595-063-450	RUBBER CUSHION
12	4			4		*MS21920-24	CLAMP (OR MS21042-26)
13	4			4		AN6-35A	BOLT
14	4			4		AN6-36A	BOLT
15	6			6		MS21042L6	NUT (OR MS21042-6)
16	18			18		AN960JD616	WASHER
17				1		*D2856-250-842	ABRASION STRIP
18				1		*D3189-3	CHAFING SHIELD
19				2		*MS21920-22	CLAMP
20		2				*D2940-1	SUPPORT
21		4				*D3595-063-530	RUBBER CUSHION
22		4				*MS21920-28	CLAMP (OR MS21042-30)
23		4				AN6-40A	BOLT
24		2				AN6-41A	BOLT
25		6				MS21042L6	NUT (OR MS21042-6)
26		18				AN960JD616	WASHER
30			1		1	*D2896-1	SUPPORT
31			2		2	*D2856-600-1009	ABRASION STRIP
32			2		2	*D3595-063-570	RUBBER CUSHION
33			4		4	*MS21920-28	CLAMP
34			2		2	*MS21920-32	CLAMP
35			4		4	AN6-40A	BOLT
36			2		2	AN6-41A	BOLT
37			6		6	MS21042L6	NUT (OR MS21042-6)
38			18		18	AN960JD616	WASHER
39			2		2	*D3189-1	CHAFING SHIELD
40					2	*D3606-1	CUFF
41					44	*CR3212-4-07	RIVET (M7885/3-4-07)
50	1	1				D3428-1	PLACARD

*REFERENCE ONLY. PARTS ARE INCLUDED IN D212-664-141/-241 OR D412-664-145/-243/-245 ASSEMBLIES ABOVE WITHOUT NOTICE

NOTE: KITS INCLUDE EXTRA HARDWARE FOR COMPATIBILITY WITH BOTH DART AND BELL/AA SKIDTUBES.

• COPYRIGHT © 2001 BY DART AEROSPACE LTD. •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: **D**
Date: 07.03.03

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WORK ORDER
NO. 31917